



Main box

To machine box  
see page 5

Power supply  
110V

Push button

M2  
M  
Side motor

Clutch  
side motion  
Y2

M4

T1

2 4 6 14  
1 3 5 13  
A1  
B2 A2

110V  
24V  
+ -

X1

S1

S2

S4

GMV SUPER STAR

GMV 274: 110

DRAWING ALL CIRCUITS DATE 021120  
FILE GMV274-110\_4 PAGE 4 OF 6

