


MAIN
POWER
TRANSFORMER


240 VAC.
10A
50/60 HZ
Connect to
Main Power
Source

Pat Trap Automatic Doubles

G-Series Wobble Wiring Diagram - 240 VAC

DRAWN BY	RNB	DATE	04-07-2004	SCALE	NTS
CHECKED BY		DATE		SHEET	1
PART NUMBER	G-WOBBLE-240V	REVISION		OF	1



		Pat Trap Automatic Doubles	
		G-Series Wiring Diagram - 120 VAC	
DRAWN BY	RNB	DATE	04-07-2004
CHECKED BY		DATE	
PART NUMBER	STANDARD TRAP	REVISION	
		SCALE	NTS
		SHEET	1
		OF	1
			1