


WESTERN SELF-LOADING ELECTRIC SKEET TRAP V1574A

<u>Cat. No.</u>	<u>Name</u>	<u>Cat. No.</u>	<u>Name</u>
V1	Base	V17	Rear Magazine Guide Rail
V2W	Frame Assembly	V18	Front Magazine Guide Rail
V3W	Gear Housing Assembly	V19W	Magazine Guide Rail Screws (Set of 3)
V4W	Gear Housing Cover and Feed Cam Assembly	V23W	Magazine Stabilizer Assembly
V5	Mainspring Housing	V24	Magazine Stabilizer Spring
V6	Solenoid Housing	V27	Carrier Arm
V7	Cocking Pawl	V28	Carrier Plate
V8	Hold-back Pawl	V28W	Carrier Assembly Complete (not shown but including items V27, V28, V29W, V32W, V34 and V35W)
V9W	Control Cam Assembly	V29W	Carrier Plate Screws (Set of 3)
V10W	Sear Assembly	V32W	Carrier Rail Assembly
V11W	Trigger Arm Assembly	V34	Carrier Rail Support
V13R	Magazine Support, Right Hand	V35W	Rail Nut Anchor with Set of Carrier Rail Bolts
V13L	Magazine Support, Left Hand	V36W	Trap grounding bolt (not shown)
V14W	Lower Magazine Bracket Assembly		
V15	Intermediate Magazine Bracket		
V16	Upper Magazine Bracket		

V1574A

Western Self-Loading *Electric* Skeet Trap Parts



WESTERN SELF-LOADING ELECTRIC SKEET TRAP V1574A


<u>Cat. No.</u>	<u>Name</u>	<u>Cat. No.</u>	<u>Name</u>
X36W	Worm Shaft Gland Assembly	V70	Sear Plunger
X37	Washer for Crank Stud and Escapement Stud	V71	Sear Spring
X39W	Mainspring Crank Assembly	V72	Sear Plunger Bushing
V40W	Mainspring Assembly	X76W	Cable Anchor Clip Assem
X42	Mainspring Adjusting Screw	V79W	Base Bolts (Set of 3 Bolts with Washers)
X43	Mainspring Swivel	X82W	Solenoid Mounting Bolts (Set of 4)
V45	Main Shaft	V84W	Switch Indicator Plate Assembly
V46	Target Escapement Cam	X87W	Screws for Gear Housing Cover or Worm Shaft Gland (Also used to pull V62 Shafts from Housing)(Set of 4)
V47W	Escapement Cam Roll Assembly	X88W	Clamp Screw Assembly for Mainspring Crank
V49	Retaining Washer for Items V47W, V209 and V215	V91W	Magazine Support Screws (Set of 2)
V50W	Escapement Lever Assembly	V92W	Magazine Bracket Bolts (Set of 2)
V51A	Escapement Lever Spring	V93W	Gear Housing Mounting Screws (Set of 4)
V52B	Escapement Cushion	X94	Key for Mainspring Crank
V57	Trigger	V105W	Main Shaft Oil Seal and Lower Bearing Assembly
V58	Trigger Pull Rod	X106	Worm Shaft Oil Seal
X58	Trigger Arm Spring	V107	Driving Worm
V59W	Trigger Mounting Bolt Assembly	V108W	Worm Gear Assembly
V60	Trigger Bushing	V110W	Planet Gear Assembly
V62	Shaft for Sear and Hold-Back Pawl	V111	Ring Gear and Ratchet
V63W	Pawl Holding Magnet Assembly	X116W	Master Switch
X65	Cocking Pawl Spring	V118A	Power Cord Assembly
V66	Firing Pin	V120A	Power Receptacle
V67	Firing Pin Guide		
V68	Firing Bar		

* A used V40W Mainspring Assembly may be returned to the factory for reconditioning with new spring and bushing.

(Note that the V40W Mainsprings are distinguished from the lighter X40W Mainsprings, listed elsewhere, by a number stamped on end of the adjusting screw plug.)

V1574A

Western Self-Loading *Electric* Skeet Trap Parts



WESTERN SELF-LOADING ELECTRIC SKEET TRAP V1574A


<u>Cat. No.</u>	<u>Name</u>	<u>Cat. No.</u>	<u>Name</u>
V125	Field Cable	X176	Ground Rod Clamp (not shown)
V126W	Outlet Box Assembly	V190W	Target Feed Arm Assembly
V128	Squeeze Type Two-Screw Connector	V191W	Target Feed Arm Pivot Assembly
X127	Release Solenoid	V192W	Target Feed Cam Roll Assembly
X129A	Motor	V194W	Feed Shelf Operating Roll Assembly
X130B	Motor Coupling	V196W	Feed Shelf Lifting Springs (Set of 2)
X132	Worm Thrust Bearing	V197W	Feed Shelf Operating Bracket Assembly
X133	Oil Filler, Drain and Level Gage Plugs, Each	V203W	Target Feed Shelf Assembly
V134W	Assorted Cotter Pins (not shown)	V205W	Target Feed Shelf Bolts (Set of 2)
V135W	Elevation Pivot Assembly	V206	Feed Shelf Shim (1/32" thick)
V136	Elevation Screw Swivel	V207AW	Target Feed Cam Assembly
V137AW	Elevation Adjusting Screw Assembly	V209A	Target Feed Finger
V141W	Tool for Guiding Main Shaft through Oil Seal	V210AW	Feed Finger Bracket Assembly
V151W	Escapement Cushion Assembly	V214	Spring for Target Feed and Stop Fingers
V155AW	Escapement Carrier Base Assembly	V215	Target Stop Finger
V157W	Escapement Cushion Cover Assembly	V216W	Stop Finger Bracket Assembly (with Bolts)
V160W	Escapement Cushion Cover Screws (Set of 2)	X190W	Stop Finger Bracket Bolts only (Set of 2)
V161W	Solenoid Housing Screws (Set of 2)		(not shown)
V163W	Motor Mounting Bolts (Set of 4)		
V173W	Motor Support Screws (Set of 2)		
X175	Ground Rod (not shown)		

V1574A

Western Self-Loading *Electric* Skeeet Trap Parts



V125




V126W



V128



X127



X129A




X130B




X132



X133



V135W



V137W



V136



V141W



V151W



V155AW



V157W



V160W



V161W



V163W



V173W



V190W



V191W



V192W




V194W



V196W



V197W



V203W




V205W



V206



V207AW



V209A



V210AW



V214



V215



V216W

